ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra

Street ID	Street Name	Significant Landmark
W1132, W1114, W1156, W1148, W1152, W1136, W1128, W	9th Main Rd, Reliable Cake Dev Residency Rd, NA, 2nd Main Rd, 7th Main Rd, 1st Crs, Gunjur-kodati Rd	saraipalya and surrounding areas

Segment No.	Total Length (m)
6/C-W1132/S114704	208.86

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	93.28	77.631957	13.046626	77.631955	13.047465	W0186	DEAD END
2	115.58	77.632369	13.047584	77.632297	13.046542	W0186	W1156

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains at saraipalya and surrounding areas in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	5000000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	

Tender	Work Details	Job No. / Work Code
Not a Tender	Improvement to Roads and Drains at saraipalya and surrounding areas in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-17-000005

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/145/2016-17	09/11/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
28/02/2017	27/02/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00

Phone No.	E-Mail ID

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
0		DARMASINGH
Date of Inspection	**Remarks**	
08/03/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1132, W1114, W1156, W1148,

ಸಹಾಯಕ ಆಯುಕ್ತರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಯಲಹಂಕ ಉಪ ವಿಭಾಗ

ಬ್ಯಾಟರಾಯನಪುರ ವಲಯ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	08/03/2017	06/04/2017	COMPLETED
SE	VASU K M	08/03/2017	06/04/2017	COMPLETED
EE	MOHAN DAS HT	08/03/2017	06/04/2017	COMPLETED
AEE	SRIDHAR	08/03/2017	06/04/2017	COMPLETED
AE	DARMASINGH	08/03/2017	06/04/2017	COMPLETED
AE	DARMASINGH	07/03/2017	06/04/2017	COMPLETED

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1132, W1114, W1156, W1148, W1152, W